

# Oil Field Environmental Incident Summary

**Incident:** 20160531113918      **Date/Time of Notice:** 05/31/2016 11:39

**Responsible Party:** WESCO OPERATING, INC.

**Well Operator:** WESCO OPERATING, INC.

**Well Name:** KOSTELECKY SWD 1

**Field Name:** DOBSON BUTTE

**Well File #:** 90050

**Date Incident:** 5/27/2016      **Time Incident:** 08:30

**Facility ID Number:**

**County:** STARK

**Twp:** 139

**Rng:** 96

**Sec:** 33

**Qtr:**

**Location Description:** inside berm located around above ground piping on north side of salt water tanks

**Submitted By:** Dave Weinert

**Received By:**

**Contact Person:** dave Weinert  
PO BOX 1650  
120 S. DURBIN STREET  
CASPER, WY 82602

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 930 Feet

**Distance Nearest Water Well:** 65 Feet

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels		
Other			20	Barrels		

**Description of Other Released Contaminant:**

Approximately 20 bls of fresh water from recipitation present within berm was also recovered.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

low

**Areal Extent:**

**Potential Environmental Impacts:**

soil within berm on facility location

**Action Taken or Planned:**

recovered fluids, replace T

**Wastes Disposal Location:** recovered fluids placed into SWD tanks on location

**Agencies Involved:**

**Updates**

---

**Date:** 5/31/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.